

### **TEXTURED TYPE 4 SURFACE**

POROUS MULTI SPORT SURFACE

## **UK Head Office:**

11/30 The Creek Northfleet Kent DA11 9AS Tel. 01474 532 277 Fax. 01474 532 288

11 Enterprise Way Jubilee Business Park Derby, DE21 4BB Tel. 01332 287410

### **Central Office:**

Fax. 01332 287413

# Scotland Office:

2E Inchmuir Road Whitehill Industrial Estate Bathgate West Lothian EH48 2EP Tel. 01506 656 779 Fax. 01506 656 838

sales@abacuspg.co.uk Website.

www.abacuspg.co.uk www.sport-top.co.uk

**MAINTENANCE** 

A controlled maintenance regime should be put in place to sustain optimum performance and drainage characteristics. Litter bins placed outside the area together with signage identifying the correct use of the surface is encouraged.

Portable equipment, if used, should be carefully carried over the surface to prevent tearing.

Litter, leaves, dirt, grit, stone, loose rubber granules and all other surface debris should be brushed, vacuumed or blown off as required. Accelerated wear may occur if this is not carried out.

The periodic removal of air borne pollution and foot carried contamination is also necessary and this can be done by cold water power washing or copious amounts of water and sweeping with a stiff brush.

A cold water power wash of 3,000 psi is usually required to remove ingrained dirt and air borne pollutants and it is recommended that this be carried out annually as a minimum requirement. Specialist cleaning contractors servicing the industry are available.

Surfacing located in damp and shaded areas may attract moss or similar. Moss, algae and light weed growth should be treated with a proprietary product ensuring care in its application with regard to the health and safety of the users. Tree sap may require a cold water power wash / chemical treatment for effective removal.

Chewing gum can be freeze hardened using an aerosol spray and carefully removed by chipping off, or alternatively, steam cleaned by specialist cleaning contractors.

Vandalism is more common on unsupervised areas. The most common forms of which are burning with cigarette lighters or with fuel assistance. Burnt areas will usually need to be cut out and repaired. Small holes can be repaired using a repair kit from us and cracking can be sealed with a glue gun.

If the surface is damaged or requires a large repair please contact us for assistance.









